BR-4-9391 B4-4-8

12 DEC 1953

MEMERANDUM FOR: The Inspector General

SUBJECT

: Working Conditions in 350 26th Street Building (Riverside Stadium)

Your report dated 25 November 1953 on the above subject has been reviewed by this Office, investigated by General Services Office, and discussed with Public Building Service engineers. The following, therefore, is mutaited in regard to action being taken on the recommendations contained in your report.

A. Cleanlinees:

- (1) Public Building Service recognizes the fact that they have been unable to obtain a highly polished curface on the asphalt tile floor. Several cleaning waxes have been tried without success as the tile absorbs the wax leaving a dull finish which gives the appearance of being dirty. The research group of Public Building Service does not recovered the use of varnishes, shellace, lacquers, etc. as these have been found to be more harmanal than cleaning compounds or wax.
- (2) Action has been taken with Public Building Service to improve the appearance of the entrance way to the building with particular emphasis as to location of trash cans. Arrangements have been made for the painting of partitions and toilets, which are also cleaned on a daily basis. It appears pertinent to point out that cleaning service as presently provided by Public Building Service is limited by the allotment of funds for the cleaning of all Government buildings and that these funds, upon a ruling of the Comptroller General, may not be increased by funds from other Government accorder.
- (3) Public Building Service advised that the installation of coco matting at entrance ways is a standard equipment and that these mats will be installed. These should remove such of the loose dirt cerried in from unpered areas.
- (b) Every effort will be made to see that dust and other residue resulting from repairs is eleaned up immediately in order that it will not be tracked over the building and will not be allowed to get into the air conditioning system.

The state of the s		
	No Change in Class. Declassified	-
Approved For Release 2001/07/12 : 🤲	0010000500 16102 Date: Nov 21 By: O 3	

(5) Public Building Service exterminator services have been utilised following each complaint of nice and insects in the building. They have agreed to furnish this service on a monthly basis, or more eften if requested.

D. Ventilation

The ventilation of this building is a subject of continual study by Public Building Fervice ongineers. The changing of air is presently accomplished by exhaust fans at each end of the building supplemented by Ilil tone of air-conditioning equipment with heating coils which are used in ventilating the building. Further, ventilating grills have been installed in the cailing and thirty-pix (36) wall or pedestal fans have been installed for circulating the air. The Public Building Tervice engineers state that the equipment now in use for the ventilation of this building is greater than that normally required for this type of space. Further, the engineers state that due to the immensity of the room and the type of lighting there will always be a base which, in their coinion, has a psychological effect on people which leads them to believe that the sir is set being changed. The engineers are still studying this mituation and will take action whenever and wherever improvements can be made.

C. Servens

A number of screens have been given to the Liaison Pivision. They have been seked to try this out and if additional screening is required to request it.

D. Concrete Sub-flooring

The installation of a concrete sub-flooring in the section of the building occupied by the Machine Division is in process. This action had been taken prior to the survey.

19/

L. K. WHITE Acting Deputy Director (Administration)

OSO - (7 Dec 53) Rewritten: SA/DDA:WHM:hh (9 Dec 53)

Distribution:

2 - 050

1 - DD/A chrono